

Estate Supervisor's Work Report – 25th March 2024 Agenda item 7.1

Lake Area

Description of work	Timeframe	Comments & Update
Bench maintenance	Seasonal	Ongoing
Large fishing Platform	September	Repair not viable. Report to follow.
Re-dress paths	Ongoing	Some paths have now been re dressed ongoing maintenance needed.
Tree works following report. Crown lifting.	Ongoing	Crown lifting the lake edge and surrounding area is in progress, some parts of the tree report have been completed

Cemetery

Description of work	Timeframe	Comments & Update
Chapel roof tile repair		completed
Ivy removal on trees	Complete	Tree report suggested removal of ivy on 2 trees other trees have also had ivy removed.

Town

Description of work	Timeframe	Comments & Update

Recreation Ground

Description of work	Timeframe	Comments & Update
Wooden posts at top boundary	ongoing	All broken posts are now replaced this will be an ongoing replacement as more of the original posts fail.
Surfacing play equipment		Wet pour surfacing has been repaired. Concrete repair still to be carried out

Estate Supervisor's Work Report – 25th March 2024 Agenda item 7.1

Arboretum

Description of work	Timeframe	Comments & Update
Tree works as recommended in tree report		Completed other than deadwood removal.

7.2 To approve expenditure for gravel for lake paths

We are running low on gravel to redress the lake paths. The price for 20 ton of 6mm to dust delivered is no more than £600 + vat.

Recommendation

To approve the expenditure of no more than £ 600 + vat from budget heading 330-4760 lake management/maintenance to purchase 20 ton of 6mm to dust for the lake paths.